

Rangeley Plt

This report shows the 2017-2019 Work Plan entries for Rangeley Plt. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Rangeley Plt in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Rangeley Plt

Asset(s): South Shore Drive

Description: 71307- WP 17 Culvert Replacement south shore

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33640	Maintenance	Corridor 5	\$12,000

Work Plan Year: 2018/19

Municipalities(s): Rangeley Plt, Sandy River Plt, Weld

Asset(s): South Shore Drive, West Side Road, Route 17, Route 16

Description: Rangeley Area 2018 LCP.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022102.00	Light Capital Paving	Varies	\$2,109,800

Local Road Assistance – Fiscal Year 2016

\$21,856

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 30.6 Shoulder Miles of Herbicide Applied
- 3.0 Drainage Structures Thawed
- 36.9 Ton(s) of Cold Patch Applied
- 32.0 Linear Feet of Guardrail or Fence Maintained
- 410.0 Linear Feet of Backhoe Ditching
- 15.2 Shoulder Miles of Sweeping
- 459.0 Linear Feet of Bridge Rail Repaired or Replaced
- 1.0 Bridge Inspection(s) Performed
- 90.7 Center Lane Mile(s) Patrolling and Inspecting
- 1.0 Drainage Structures Installed or Replaced
- 1.0 Bridge(s) Washed
- 200.0 Linear Feet of Shoulder Rebuilt
- 1,512.0 Sq Feet of Bridge Wearing Surface Repaired