

Photo 1 (1/24/18): View of the lower dam and Site buildings from the Route 1 bridge, looking NW.



Photo 2 (1/24/18): View of the southeast corner of the Site from the Route 1 bridge, looking north.



Photo 3 (7/20/18): Entrance to the Site from Route 1. Stream S9 is visible in the grass along with monitoring well GWW103. Photo taken from driveway entrance, looking west.



Photo 4 (10/12/18): Fall vegetation for wetland W9. Photo taken from lawn next to stream S9, looking west.



Photo 5 (10/12/18): Stream S9 adjacent to wetland W9 (left) and behind the existing Site garage buildings. Photo taken from the stream bank, looking south.



Photo 6 (4/25/19): Stream S9 adjacent to wetland W9 (top) and behind the existing Site garage buildings. Photo taken from dirt lot, looking east with yellow piezometers in background.



Photo 7 (1/24/18): Existing Site garage buildings, looking north.



Photo 8 (3/6/18): View from Site garage buildings looking east towards Route 1 across developed portions of the Site.



Photo 9 (3/6/18): Existing Belfast Water District office building located next to the lower dam, photo taken looking east.



Photo 10 (10/24/18): View of the Lower Reservoir and dam looking east from the shoreline hiking trail.



Photo 11 (10/12/18): View from Site access road looking east towards the Site garage buildings and developed areas.

Monitoring well GWW101 is visible on the left.



Photo 12 (10/12/18): View from the Site access road looking north west at the first clearing where wetland W5 is located.

Photograph Log



Photo 13 (10/12/18): View of small field mapped as wetland W5, looking northeast, following landowner use for logging activities. Planted evergreen stand visible in background.



Photo 14 (10/12/18): View of small field looking west, following landowner logging activities.



Photo 15 (9/7/18): View of small field and evergreen stand identified as part of wetland W5, looking northwest.



Photo 16 (8/24/18): View of the large hay field comprising the northeast portion of the Site. Photo was taken looking northwest out across the entire field.



Photo 17 (8/24/18): View looking south at the headwaters of stream S10 located in the Site hay field.



Photo 18 (8/24/18): Representative photo of the upper portions of stream S9, located between wetlands W16 and W17.

Photograph Log



Photo 19 (8/24/18): View of the Site hayfield from the field's SW corner, looking north east. Vegetation associated with wetland W1 is visible in the foreground.



Photo 20 (11/12/18): View, looking east, of the gravel road constructed in the Site hayfield for drill rig access.



Photo 21 (10/12/18): View, looking west, of logging access road upon leaving the small Site field.



Photo 22 (10/29/18): Photo of stream S6, looking north.



Photo 23 (10/12/18): Photo representing the typical views of the Site from the logging road, with evidence of both recent and older logging acitivies by the property owner.



Photo 24 (10/12/18): Free-flowing portion of the Little River, between the Upper and Lower Reservoirs, looking north.

Photograph Log



Photo 25 (9/6/18): Looking east along the pipeline easement on the Eckrote property.



Photo 26 (9/6/18): View of the shoreline from the pipeline easement, looking northeast.



Photo 27 (9/6/18): View of the shoreline from the pipeline easement looking east, with the wetland W11 salt marsh in the foreground.



Photo 28 (8/24/18): Intertidal mudflats from the Eckrote property shore, looking southeast.

Please refer to the included Photo Georeference Map for the locations of each photo as depicted on the wetlands and streams survey map for the Site.

Photo Georeference Map

