

Structures in the Municipality of Lily Bay Twp

CONDITION RATINGS

TOWN1: Lily Bay Twp	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 7 Good
BRIDGE NO.: 6148	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 1.3 MI N OF BEAVER COVE	YEAR BUILT: 1969	DECK CONDITION: 7 Good
BRDGNAME: LILY BAY	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 5 Fair
OWNER: 1 State DOT	SPAN TYPE: 3 Slab	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: LILY BAY RD (SA1)	STRUCTURE LENGTH IN FEET: 33	DATE OF INSPECTION: 11/13/2012
FEATURE UNDER: LILY BAY STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 88.9
ROAD INV NO: 0002100306	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 29 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Lily Bay Twp

CONDITION RATINGS

TOWN1: Lily Bay Twp	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 7 Good
BRIDGE NO.: 5455	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 1 MI N OF BEAVER COVE	YEAR BUILT: 1952	DECK CONDITION: 6 Satisfactory
BRDGNAME: SOUTH BROOK	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 5 Fair
OWNER: 1 State DOT	SPAN TYPE: 3 Slab	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: LILY BAY ROAD (SA1	STRUCTURE LENGTH IN FEET: 25	DATE OF INSPECTION: 11/13/2012
FEATURE UNDER: SOUTH BROOK	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 83.7
ROAD INV NO: 0002100306	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 29 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		