

Photo Log for Accident Investigation for Deropement of Spillway East

Photo 1 -Spillway East lift line on ground

Photo 2 - Tower 8 after deropement

Photo 3 - Tower 8 showing broken stiffener

Photo 4 -Attachment point of incoming 4-sheave assembly to the main walking beam on the outgoing side

Photo 5 -Rope catcher on the outgoing 4-sheave assembly

Photo 6- Brittle bar and rope catcher on the incoming 4-sheave assembly

Photo 7- Sheave showing low outside flange

Photo 8 - Main walking beam attachment point to outgoing 4-sheave assembly

Photo 9- Damaged crossarm mounting bracket

Photo 10 -Sheave number 7, pairing beam arrangement and connection to 4-sheave assembly walking beam and new fasteners for retaining the sheave liner

PHOTO 1



PHOTO 2



PHOTO 3



PHOTO 4



PHOTO 5



PHOTO 6



PHOTO 7



PHOTO 8




PHOTO 9



PHOTO 10

