



Standard Operating Procedure
Bureau of Water Quality Date: April
20, 2006
Revised: June 12, 2017
Doc num: DEPLW0768

**Bureau of Water Quality
Division of Water Quality Management
Industrial Stormwater Program**

Standard Operating Procedures and Visual Monitoring Guidelines
for Stormwater Discharges Associated With Industrial Activities.

1. **APPLICABILITY.** This Standard Operating Procedure (SOP) applies to all industrial facilities covered under Maine's Multi-Sector General Permit (MSGP) for Stormwater Discharges Associated with Industrial Activity. Permitted facilities are required to perform quarterly visual monitoring of their stormwater discharges and record and maintain the results in the facility's Stormwater Pollution Prevention Plans (SWPPP).

Monitoring requirements are not required for entities that are participating in a Watershed Management Plan. The Long Creek Watershed Management Plan in the municipalities of South Portland, Portland, Westbrook and Scarborough is a Department Approved Watershed Management Plan. In addition, the requirements for visual monitoring does not apply at a facility that is inactive and unstaffed, provided that there are no industrial materials or activities exposed to stormwater. To invoke this exception, the permittee must maintain a signed and certified statement with the facility SWPPP stating that the site is inactive and unstaffed, and that there is no exposure to stormwater.

2. **PURPOSE.** This document provides guidelines for standardized collection and visual examination of quarterly visual monitoring samples for indicators of stormwater pollution as defined in Special Condition N. of the MSGP and to provide guidelines describing standardized methods of data recording and record keeping of all quarterly visual stormwater discharge monitoring data as described in Special Condition N. of the MSGP.

3. **DEFINITIONS.**

- 3.1. **MULTI-SECTOR GENERAL PERMIT (MSGP).** A general permit for Stormwater Discharges Associated with Industrial Activity. Authorizes the direct discharge or point source discharge of stormwater associated with industrial activity to waters of the State (other than groundwater) or to an MS4 (which discharges to waters of the State), provided the discharge meets the requirements stated in this permit. This permit is effective March 7, 2017 and expires March 7, 2022. It replaces Maine's 2011 MSGP for Industrial Activity issued April 26, 2011.
- 3.2. **SWPPP.** Stormwater Pollution Prevention Plan. A written plan developed and implemented by each permitted facility to reduce or eliminate pollutants which come in contact with stormwater associated with industrial activity. This plan outlines sources of potential stormwater pollutants and the methods by which these pollutants will be reduced or prevented from entering waters of the State.

Standard Operating Procedure Guidelines For Visual Monitoring of Stormwater Discharges Associated With Industrial Activities. Division of Water Quality Management, Industrial Stormwater Program



- 3.3. GRAB SAMPLE. A single sample or collection of stormwater taken during a qualifying storm event from a single stormwater outfall. The sample may be collected manually or with an automatic sampler.
- 3.4. OUTFALL. The location where collected and concentrated stormwater flows are discharged from the facility such that the first receiving waterbody into which the discharge flows, either directly or through a separate storm sewer system, is a water of the State.
- 3.5. QUALIFYING STORM EVENT. A storm event that is either precipitation, ice or snow melt that produces a measureable discharge of 0.1 inch or more in a 24-hour period at an outfall and occurs at least 72 hours from a previous qualifying storm event.

4. RESPONSIBILITIES.

- 4.1. MONITORING PROGRAM IMPLEMENTATION. The visual monitoring schedule listed below in this section is also outlined in Maine's 2016 MSGP Special Condition N. Visual examinations must be clearly documented and maintained in the facility's SWPPP. The permittee shall perform and document a quarterly visual examination of industrial stormwater discharges from each outfall which discharges stormwater associated with industrial activity from the facility.
- 4.2. OUTFALL IDENTIFICATION. The permittee shall identify each industrial stormwater outfall at the facility. All outfalls must be clearly identified on the facility site map which is part of the facility's SWPPP and presented in the written text of the SWPPP.
- 4.3. REPRESENTATIVE OUTFALLS. "Representative outfalls" mean two or more outfalls with a single drainage area that are anticipated to discharge substantially similar pollutants resulting from substantially similar industrial activities, materials, or practices occurring within the outfalls' designated drainage area. If the facility contains representative outfalls, visual monitoring may be conducted at one of the outfalls during a given monitoring period provided that subsequent samples are taken from a different outfall within the representative outfalls' drainage area. The facility is not required to monitor more than one representative outfall within a designated drainage area per monitoring event as long as the site's SWPPP contains the required information as identified in Special Condition B(15) of the MSGP.
- 4.4. EMPLOYEE TRAINING. The permittee shall ensure that all facility personnel involved in stormwater sampling are properly trained. Staff involved in sampling shall:
 - a. Be familiar with the site map and outfall locations
 - b. Walk the site to physically identify each sampling location
 - c. Become familiar with local rainfall and drainage patterns
 - d. Become competent with proper sample collection procedures



Personnel involved in sampling should also be trained in all facility safety procedures as they apply to stormwater sampling. If possible, the same individual should carry out the collection and examination of discharges for the entire permit term. Written documentation signed by a qualified person certifying that all personnel involved in sampling have been properly trained should be documented in the SWPPP.

- 4.5. **SAMPLE COLLECTION FREQUENCY.** Visual examination of industrial stormwater discharges must be performed once per monitoring quarter. If a qualifying storm event does not occur at the facility for a particular monitoring quarter, the permittee is excused from visual monitoring for that quarter, provided the permittee documents in the monitoring records that no qualifying event occurred. The Visual Monitoring Form shall be used to document both qualifying and non-qualifying storm events. Schedule of monitoring quarters is listed below.

- First: January 1 – March 31
- Second: April 1 – June 30
- Third: July 1 – September 30
- Fourth: October 1 – December 31

All other time specific sampling requirements are to be performed in accordance with the parameters outlined in the procedures section of this document.

- 4.6. **RECORD KEEPING AND REPORTING.** The permittee shall maintain all visual monitoring reports/records onsite with the SWPPP. The permittee is not required to submit visual monitoring results to DEP unless specifically requested to do so.. Requirements for recording visual examination data are outlined in the procedures section of this document.

5. PROCEDURES

- 5.1. **SAMPLE COLLECTION TIMING.** A grab sample must be collected from each facility outfall (except representative outfalls) once per quarter during a qualifying storm event. During a qualifying storm event, a grab sample for visual examination should be collected during the first 60 minutes or as soon thereafter, but must not to exceed 2.25 hours of when runoff begins discharging from an outfall. During monitoring quarters when snow or icemelt represents the only stormwater discharge, a grab sample must also be collected during periods of significant snow or ice melt within the first 60 minutes or as soon thereafter, but not to exceed 2.25 hours of when snow or icemelt begins discharging from an outfall. Stormwater runoff from employee parking lots, administration buildings, and landscaped areas that is not mixed with stormwater associated with industrial activity, or stormwater discharges to municipal sanitary sewers does not need to be sampled. Samples must be collected during daylight hours and normal operations.



- 5.2. **SAMPLE CONTAINER CLEANING AND PREPARATION.** The facility should have an adequate supply of containers prepared for collection of industrial stormwater samples from each outfall prior to collecting samples for visual examination. All sample containers used for sampling for visual examination should be certified as clean and free of residue. After each use and for cleaning the Imhoff Settling Cone or graduated beaker. A bottle brush will aid in removing any fine sediment trapped in the bottom point of the Imhoff cone:
- Wash containers in a non-phosphate detergent and tap water wash.
 - Thoroughly fill and rinse containers with tap water at least three (3) times.
 - Store containers closed, and in an area free of dust and other potential sample contaminants.
 - If additional containers are needed to collect samples from less accessible outfalls (e.g. buckets which are attached to poles for reaching outfalls), these containers should also be cleaned and prepared as indicated above.
- 5.3 **MANUAL GRAB SAMPLE COLLECTION.** Manual grab samples should be collected by inserting a container under or downstream of a discharge with the container opening facing upstream, and with the opening of the container completely immersed under water, whenever possible. A sample container at least 1000 ml should be used to collect the sample. In most cases the sample container can be held in hand while the sample is collected. Less accessible outfalls may require the use of poles and buckets to collect grab samples. Take the grab from the horizontal and vertical center of the outfall. If sampling in a channel, (e.g., ditch, trench, rill) avoid stirring up bottom sediments. Avoid touching the inside of the container to prevent contamination. Transfer sample to a clear glass or plastic container if using another container such as a bucket to collect a sample from a less accessible location. If taking samples from multiple outfalls, label containers with outfall identification prior to taking samples. Make sure samples are securely capped until examination.
- 5.4 **COLLECTION OF GRAB SAMPLES BY AUTOMATIC SAMPLER.** Facilities which use automatic samplers for stormwater sampling may collect grab samples for visual examination by this method. Programming for collecting grab samples is specific to the type of automatic sampler. All facility personnel who collect stormwater samples using automatic samplers should be properly trained in operation of the sampler before doing so. Several different types of automatic samplers are available for stormwater sampling. However, the following guidelines should be followed when sampling regardless of the type of sampler used. All equipment must be properly cleaned, particularly the tubing and sample containers. Deionized water should be drawn through the sampler to remove any residuals prior to taking samples. Tubing should also be periodically replaced to avoid algae or bacterial growth. Additionally, a distilled/deionized water blank



sample should be taken at each outfall sampled to determine if contamination of storm-water samples by the sampling equipment has occurred. Samplers should be used in exact accordance with the manufacturers' instructions. All sampler calibration and maintenance data should be kept on site with the SWPPP.

- 5.5 **SAMPLE EXAMINATION.** Visual examination of all grab samples collected must be performed within the first sixty (60) minutes. Bring the collected samples to a well lit indoor area. Pour each sample into a separate 1 L polycarbonate plastic graduated Imhoff settling cone or 1000 ml graduated cylinder. The Imhoff settling cone or beaker should have graduations that allow volume measurement to the nearest 10 milliliter. Record the total sample volume to the nearest milliliter on the visual monitoring form. Examine the samples for the following criteria according to the instructions provided with the visual monitoring form: Foam, odor, clarity, floating solids, suspended solids, color, oil sheen, settled solids, and any other obvious indicators of stormwater pollution. Read the settled solids 1 hour after pouring the sample into the cone, as this assures that all solids are settled out of the water. Settled solids in the bottom of the cone should be measured to the nearest milliliter.

*Note: Clear polycarbonate plastic Imhoff cones are available from several scientific supply companies. You may also purchase 1000 ml graduated beakers from various scientific supply companies.

- 5.6 **SAMPLE DATA RECORDING.** Record all sample data on the visual monitoring form after examining the sample for all of the criteria listed in the instructions. The form should include the examination date and time, examination personnel, the nature of the discharge (e.g., rain, snow or icemelt), identification of outfall sampled, quality of the stormwater discharge (including observations of color, odor, clarity, floating solids, settled solids, suspended solids, foam, oil sheen, and any other obvious indicators of stormwater pollution), and probable sources of any observed contamination including any corrective actions taken. The permittee must sign and certify the documentation in accordance with Standard Condition 2 of the Maine MSGP. All visual examination reports must be maintained with the facility SWPPP.

- 5.7 **RECOMMENDATIONS FOR SOLVING SAMPLE LOCATION PROBLEMS.** Consult guidelines listed below when it is necessary to sample an outfall located at a less than ideal location for sampling.

- **PROBLEM:** Sampling where stormwater comingles with process water or other non-stormwater discharge.

RECOMMENDATION: Attempt to sample the stormwater discharge before it mixes with the non-stormwater discharge. If this is impossible, sample the discharge and maintain a record of the visual examination data observed under both conditions on site with the



SWPPP. This will provide an indication of the contribution of any observable contamination from each source.

- **PROBLEM:** Numerous small point channels make up an outfall from which it is difficult to collect a sample.

RECOMMENDATION: Impound channels or join their flow together by building a weir or digging a ditch to collect discharge at a low point for sampling. This artificial collection point should be lined with plastic or filter fabric and stone to prevent infiltration and/or high levels of sediment.

- **PROBLEM:** Inaccessible discharge point. Examples include underwater discharges or unreachable discharges (e.g., out of a cliff, steep slope or bank of a stream).

RECOMMENDATION: Go up the pipe to sample (e.g., to the nearest manhole or inspection point). If these are not available, tap into the pipe, or sample at several locations upstream of the pipe if the pipe is the only outfall for the facility.

- **PROBLEM:** Managing multiple sampling sites to collect grab samples during the first 60 minutes of a measurable storm event.

RECOMMENDATION: Have a sampling crew ready to help when forecasts indicate that a measurable storm event is likely to occur. If this is not possible, sample the missed outfall locations during other measurable storm events and record this circumstance in the SWPPP.

- **PROBLEM:** Commingling of parking lot runoff with discharge associated with industrial activity.

RECOMMENDATION: The combined runoff must be sampled at the discharge point as near as possible to the industrial activity or at the parking lot drain inlet if there is one.

- **PROBLEM:** Sampling in manholes.

RECOMMENDATION: Sample with a collection device on the end of a pole to reach stormwater. Personnel sampling in manholes should have confined space safety training and ambient air monitoring sampling devices if manholes have to be entered.

- **PROBLEM:** Run-on from other property.

RECOMMENDATION: If possible, collect and examine a sample of the stormwater at the border of the property where the run-on occurs. Then, collect and examine a sample of the stormwater at a facility outfall downstream of the run-on point. Note any ob-



Standard Operating Procedure
Bureau of Water Quality Date: April
20, 2006
Revised: June 12, 2017
Doc num: DEPLW0768

servable differences between the samples and maintain the documentation with the SWPPP.

- When confronted with other difficult sampling scenarios not addressed above, the permittee should consult DEP for guidance on how to best address the situation.

6. REFERENCES

- 5.5** GUIDANCE MANUAL FOR THE MONITORING AND REPORTING REQUIREMENTS OF THE NPDES MULTI-SECTOR STORM WATER GENERAL PERMIT
United States Environmental Protection Agency, Office of Water (EN-336), EPA 833-B-99-001(January, 1999)
- 5.6** NPDES STORM WATER SAMPLING GUIDANCE DOCUMENT
United States Environmental Protection Agency, Office of Water (EN-336), EPA 833-8-92-001 (July, 1992)
- 5.7** STATE OF MAINE DEPARTMENT OF ENVIRONMENTAL PROTECTION MULTI-SECTOR GENERAL PERMIT MAINE POLLUTANT DISCHARGE ELIMINATION SYSTEM STORMWATER DISCHARGE ASSOCIATED WITH INDUSTRIAL ACTIVITY
Maine Department of Environmental Protection, Bureau Water Quality, Waste Discharge License # W-008227-MN-C-RR (Dec. 2016)