

Assessment for: Fall Line Condos@ Sunday River, ME0092005  
Location: Newry  
Date: June 25, 2009

**Summary of the Data used in our Assessment**

Well type: Drilled Well  
Well identification number: 92005101  
Well description: 503 Ft Drilled Well  
Overburden thickness (feet): Not Known  
Positive bacteria test result(s): Yes  
Nitrate test result(s) greater than 5 ppm: No  
Septic system(s) within 300 feet of the well: No  
Animal feedlots/manure piles(s) within 300 feet of the well: No

**Risk Based on Well Type and Site Geology**

*Ranking:*

Well type: Drilled Well  
Overburden thickness (feet): Unknown

*Existing risk of contamination  
based on well type & site geology:*

**Moderate risk**

**Existing Risk of Acute Contamination**

*Ranking:*

Positive coliform test(s): Yes  
Nitrate test(s) greater than 5 ppm: No  
Septic system(s) within 300 feet of the well: No  
Animal feedlot(s)/manure pile(s) within 300 feet of the well: No

*Existing risk of acute contamination:*

**High risk**

**Future Risk for Acute Contamination**

*Ranking:*

Status of land control: *The owner owns the land within 300 ft of the well*

*Future risk of acute contamination:*

**Low risk**