




30 Park Drive Topsham, ME USA 04086 Phone (207) 729-1199 Prepared by EPL on 2022-02-02

Reviewed by TM on 2022-02-02 50347_DikeBridge_Ex_Alt10.mxd

<u>Notes</u>

1. Existing conditions are based on 2021 tidal stage data that was collected after leaking gates were fixed and 2021 drone imagery collected by MaineDOT before the leaking gates were fixed and represent a range of potential existing conditions. 2. Approximate water surface elevations (WSEL) for proposed alternatives are based on the 2021 Phase 1 and Phase 2 hydraulics analyses using tidal stage data collected by MaineDOT in 2021.

- 3. Coordinate System: NAD 1983 UTM Zone 19N FT
- 4. Vertical Datum: NAVD88
- 5. Aerial imagery in the project area was obtained by unmanned aircraft vehicle (UAV) by MaineDOT on July 20, 2021.
- 6. Aerial imagery surrounding the project area is provided by ArcGIS Online World Imagery Mapping Service
- (http://server.arcgisonline.com/arcgis/services/World_Imagery/MapServer).
- 7. TIN Surface information is based on survey data provided by the Maine Department of Transportation.



Client/Project Maine DOT

Dike Bridge Machias, Maine

Figure No. Alt 10-Ex



Landward Water Levels for Typical Tides and River Flows 2/2/2022