

Eliot

This report shows the 2017-2019 Work Plan entries for Eliot. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Eliot in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Eliot

Asset(s): State Road

Description: Sturgeon Creek Bridge (No.3310) over Sturgeon Creek. Located 0.13 of a mile north of Creek Crossing Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021856.00	Bridge Painting	4	\$200,000

Work Plan Year: 2017

Municipalities(s): Eliot, South Berwick

Asset(s): Route 236

Description: Connectivity improvements.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
018754.00	Environmental Construction - Wildlife	1	\$80,000

Work Plan Year: 2017

Municipalities(s): Eliot, South Berwick, York

Asset(s): Route 91

Description: Beginning at Scotland Bridge Road in York and extending northwest 3.75 miles.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022500.00	Highway Improvement-PE Only	3	\$215,000

Work Plan Year: 2017

Municipalities(s): Eliot, Kittery, South Berwick, York

Asset(s): Route 91, State Road, Route 101, Beech Ridge Road, Beech Road, Route 103, Route103

Description: Rangeley Plt. to Rangeley 2017 LCP

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
024009.00	Light Capital Paving	Varies	\$886,700

Work Plan Year: 2017

Municipalities(s): Eliot, South Berwick

Asset(s): Route 101

Description: Tree and brush removal on Route 101 in Eliot

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33226	Maintenance	Corridor 4	\$39,700

Work Plan Year: 2017

Municipalities(s): Eliot, South Berwick

Asset(s): Route 101

Description: ELIOT LCP CY 2017 Ditching Route 101

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33219	Maintenance	Corridor 4	\$86,700

Work Plan Year: 2017

Municipalities(s): Eliot

Asset(s): Beech Road

Description: ELIOT LCP CY 2017 Ditching Beech Road in Eliot

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33217	Maintenance	Corridor 4	\$14,500
Work Plan Year: 2017 Municipalities(s): Eliot Asset(s): Route 103 Description: ELIOT LCP CY 2017 Ditching Route 103 Eliot			
WR 33216	Maintenance	Corridor 4	\$57,800
Work Plan Year: 2017 Municipalities(s): Eliot Asset(s): State Road Description: ELIOT LCP CY 2017 Ditching State Road in Eliot			
WR 33215	Maintenance	Corridor 4	\$11,600
Work Plan Year: 2017 Municipalities(s): Eliot, York Asset(s): Beech Ridge Road Description: ELIOT LCP CY 2017 Ditching/Culvert Beech RidgeRd			
WR 33220	Maintenance	Corridor 5	\$32,800
Work Plan Year: 2017 Municipalities(s): Eliot Asset(s): Route 101 Description: ELIOT LCP CY 2017 Culverts Route 101			
WR 33240	Maintenance	Corridor 4	\$31,300
Work Plan Year: 2017 Municipalities(s): Eliot, York Asset(s): Route 103 Description: ELIOT LCP CY 2017 Culverts Route 103 Eliot /York			
WR 33262	Maintenance	Corridor 4	\$11,700
Work Plan Year: 2018/19 Municipalities(s): Eliot Asset(s): Route 236 Description: Located at the intersection of Route 236 and Depot Road.			
019429.00	Intersection Improvements W/O Signal	1	\$2,525,000

Local Road Assistance – Fiscal Year 2016

\$34,248

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 125.0 Linear Feet of Shoulder Rebuilt
- 12.0 Emergency Event Responses
- 11.0 Drainage Structures Cleaned
- 5.0 Drainage Structures Installed or Replaced
- 43.2 Ton(s) of Cold Patch Applied
- 68.0 Center Lane Mile(s) Patrolling and Inspecting

16.9 Shoulder Miles of Litter and Debris Removal
60.0 Linear Feet of Guardrail or Fence Maintained
1,350.0 Linear Feet of Backhoe Ditching
35.0 Minor Sign(s) Installed or Maintained
288.0 Trees Removed
15,425.0 Linear Feet of Brush Removed
1.0 Bridge(s) Washed
24.3 Miles of Striping Applied
