

York

This report shows the 2017-2019 Work Plan entries for York. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to York in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): York

Asset(s): Beech Ridge Road

Description: Barrell Bridge (No.3500) over Dolly Gordon Brook. Located 0.32 of a mile southeast of Saltwater Drive.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
018957.00	Bridge Replacement	5	\$1,255,000

Work Plan Year: 2017

Municipalities(s): York

Asset(s): Scotland Bridge Road

Description: Scotland Bridge (No.2750) over York River. Located 0.05 of a mile north of Major McIntire Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
018985.00	Bridge Wearing Surface Replacement	6	\$250,000

Work Plan Year: 2017

Municipalities(s): Eliot, South Berwick, York

Asset(s): Route 91

Description: Beginning at Scotland Bridge Road in York and extending northwest 3.75 miles.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022500.00	Highway Improvement-PE Only	3	\$215,000

Work Plan Year: 2017

Municipalities(s): Eliot, Kittery, South Berwick, York

Asset(s): Route 91, State Road, Route 101, Beech Ridge Road, Beech Road, Route 103, Route103

Description: Rangeley Plt. to Rangeley 2017 LCP

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
024009.00	Light Capital Paving	Varies	\$886,700

Work Plan Year: 2017

Municipalities(s): Eliot, York

Asset(s): Beech Ridge Road

Description: ELIOT LCP CY 2017 Ditching/Culvert Beech RidgeRd

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33220	Maintenance	Corridor 5	\$32,800

Work Plan Year: 2017

Municipalities(s): York

Asset(s): Route 103

Description: ELIOT LCP CY 2017 Ditching Route 103 in York

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33221	Maintenance	Corridor 4	\$11,500

Work Plan Year: 2017

Municipalities(s): Eliot, York

Asset(s): Route 103

Description: ELIOT LCP CY 2017 Culverts Route 103 Eliot /York

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33262	Maintenance	Corridor 4	\$11,700
Work Plan Year: 2018/19			
Municipalities(s): York			
Asset(s): Route 1			
Description: Rice's Bridge (No.2715) over York River. Located 0.12 of a mile west of Ferry Lane.			
ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021761.00	Bridge Protective Coating	1	\$200,000
Work Plan Year: 2018/19			
Municipalities(s): York			
Asset(s): Route 1			
Description: Cape Neddick Bridge (No.2127) over Cape Neddick River. Located 0.12 of a mile north of Route 1A.			
ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021709.00	Bridge Replacement	1	\$1,200,000
Work Plan Year: 2018/19			
Municipalities(s): York			
Asset(s): Route 1A			
Description: Located at the intersection of Route 1A and Long Sands Road. KACTS Sponsored.			
ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021651.00	Intersection Improvements W/O Signal	4	\$545,100
Work Plan Year: 2018/19			
Municipalities(s): York			
Asset(s): Route 1			
Description: Located at the intersection of Route 1 and New Connector Road. KACTS Sponsored.			
ID	Scope of Work	Highway Corridor Priority	Estimated Funding
020899.00	Traffic Signals	1	\$689,000

Local Road Assistance – Fiscal Year 2016

\$229,932

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 104.0 Linear Feet of Guardrail or Fence Maintained
- 7.0 Bridge(s) Cleaned
- 1.0 Bridge Inspection(s) Performed
- 7.0 Emergency Event Responses
- 23.6 Miles of Striping Applied
- 42.0 Ton(s) of Cold Patch Applied
- 500.0 Linear Feet of Shoulder Rebuilt
- 100.0 Linear Feet of Backhoe Ditching
- 20.0 Minor Sign(s) Installed or Maintained
- 17.0 Center Lane Mile(s) Patrolling and Inspecting
- 11.0 Bridge(s) Washed