

Black Nubble Wind Farm
 Bridge Inspection Trip, Saturday 12/04/04
 Taken by Bill Connors, EEC and Roger Gagnon, Gagnon Engineering, Inc.
 (Bridge #1 photos 20-27 are from an earlier trip, Oct 2004)

Bridge Trip #1		Bridge Trip #2	
Photo #	Description	Photo #	Description
1	Box Culvert Maint, west side	1	Bridge 1, underneath, lk east
2	Box Culvert Maint, east side	2	Bridge 1, underneath, lk east
3	Bridge #5, east abut, fr north	3	Bridge 1, underneath, lk east
4	Bridge #5, underneath, lk west	4	Bridge 1, west abut, fr south
5	Bridge #5, west abut, fr south- note sister I-beam, center-span	5	Bridge 1, east abut, fr south
6	Bridge #5, deck, lk west	6	Bridge 1, deck, lkg east
7	Bridge 6, north abut, fr west	7	4 moose on BN road, shale pit
8	Bridge 6, underneath, lk south	8	New Bridge #1, north of flagged crossing, lkg north
9	Bridge 6, south abut, fr east – note the wing wall bulge	9	NB #1, at crossing, lkg east
10	Bridge 6, south about, fr west	10	NB #1, at crossing, lkg east
11	Bridge 6, deck, looking north	11	NB #1, south of crossing, showing ravine depth
12	Box Culvert South, east side	12	NB #1, south of flagged crossing, looking south
13	Box Culvert South, west side	13	Bridge 4, west side, culvert is 4' X 6', only 18" road cover
14	Box Culvert North, west side	14	Bridge 4, west side
15	Box Culvert North, east side	15	Bridge 4, east side
16	Bridge 7, from east lkg south	16	Culvert at C10 near Bridge 4
17	Bridge 7, deck, looking	17	Culvert at C10, only 1' of road surface cover
18	Bridge 7, from west lkg north	18	Bridge 3, south abut, fr east
19	Bridge 7, from west lkg north	19	Bridge 3, underside, lkg north
20	Coplin Schoolhouse - Sign	20	Bridge 3, north abut, fr west
21	Coplin Schoolhouse	21	Bridge 3, deck, lkg north
22	Coplin Schoolhouse	22	Bridge 2, west abut, fr south, south beam not supported well
23	Coplin Schoolhouse	23	Bridge 2, east abut, fr south
24	Moose jaw, West Redington	24	Bridge 2, underside – 2 beams, 3' high, 7' spacing
25	Moose bone, West Redington	25	Bridge 2, west abut, fr south
26	Bear sign, West Redington Rd	26	Bridge 2, deck, lkg west
27	Bear sign, West Redington Rd	27	Culvert at C5, "old oil tank"