

## Exeter

This report shows the 2017-2019 Work Plan entries for Exeter. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Exeter in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

### Planned Capital and Maintenance Work 2017-2019

**Work Plan Year:** 2017

**Municipalities(s):** Exeter, Stetson

**Asset(s):** Exeter Road

**Description:** Clarks Hill Road / Exeter Road (407)

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 32429	Maintenance	Corridor 5	\$106,100

**Work Plan Year:** 2018/19

**Municipalities(s):** Bradford, Corinna, Corinth, Exeter, Garland, Kenduskeag, Levant, Milo, Newport, Orneville Twp, Palmyra, Pittsfield, Stetson

**Asset(s):** Peltoma Avenue, Route 11, Avenue Road, Nokomis Road, Williams Road, Madawaska Road, Garland Road, St

**Description:** Stetson Area 2018 LCP.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022110.00	Light Capital Paving	Varies	\$2,194,800

### Local Road Assistance – Fiscal Year 2016

\$35,340

### Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 3.0 Emergency Event Responses
- 1.0 Drainage Structures Installed or Replaced
- 2.0 Bridge(s) Washed
- 17.3 Miles of Striping Applied
- 123.5 Center Lane Mile(s) Patrolling and Inspecting
- 59,560.7 Linear Feet of Grader Ditching
- 8.4 Shoulder Miles of Sweeping
- 5.0 Trees Removed
- 17.0 Minor Sign(s) Installed or Maintained
- 747.0 Linear Feet of Backhoe Ditching
- 258.4 Linear Feet of Brush Removed
- 1.0 Bridge Inspection(s) Performed
- 24.0 Ton(s) of Cold Patch Applied
- 1.0 Drainage Structures Repaired
- 903.0 Linear Feet of Shoulder Rebuilt
- 18.5 Shoulder Miles of Mowing