

Monticello

This report shows the 2017-2019 Work Plan entries for Monticello. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Monticello in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Monticello

Asset(s): Fletcher Road

Description: 71505 Fletcher road

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 32866	Maintenance	Corridor 5	\$23,000

Work Plan Year: 2018/19

Municipalities(s): Brookton Twp, Danforth, Forest City Twp, Forest Twp, Monticello, Prentiss Twp T7 R3 NBPP, T8 R3 NBPP, T8 R4 NBPP

Asset(s): Fletcher Road, Forest City Road, Route 169

Description: Houlton Area 2018 LCP.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022116.00	Light Capital Paving	5	\$1,290,900

Local Road Assistance – Fiscal Year 2016

\$39,392

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 11.0 Emergency Event Responses
- 2,043.3 Center Lane Mile(s) Patrolling and Inspecting
- 160.0 Sq Feet of Pavement Legend Applied
 - 0.6 Ton(s) of Cold Patch Applied
- 34.0 Shoulder Miles of Litter and Debris Removal
- 24.0 Linear Feet of Bridge/Main Support Members Replaced or Repaired
 - 1.0 Linear Feet of Bridge Rail Repaired or Replaced
 - 1.0 Bridge(s) Washed
- 48.0 Linear Feet of Bridge Joints Repaired or Replaced
- 25.0 Linear Feet of Brush Removed
 - 1.0 Bridge(s) Cleaned
- 2.0 Bridge Inspection(s) Performed