

Structures in the Municipality of Andover West Surplus

CONDITION RATINGS

| | | |
|--|--|--|
| TOWN1: <input type="text" value="Andover West Surplus"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="5919"/> | BRIDGE REGION: <input type="text" value="Western"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| LOCATION: <input type="text" value="0.1 MI W OF ANDOVER TL"/> | YEAR BUILT: <input type="text" value="1963"/> | DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRDGNAME: <input type="text" value="FRYE"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| OWNER: <input type="text" value="4 Municipal"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="4 Municipal"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| FEATURE ON: <input type="text" value="S.A.1 (UPTON ROAD)"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="37"/> | DATE OF INSPECTION: <input type="text" value="5/2/2011"/> |
| FEATURE UNDER: <input type="text" value="FRYE BROOK"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="91.7"/> |
| ROAD INV NO: <input type="text" value="0001700306"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="25"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="LOW USE/REDUNDANT BRIDGE"/> | | |