

Structures in the Municipality of Dennysville

CONDITION RATINGS

TOWN1: <input type="text" value="Dennysville"/>	TOWN2: <input type="text" value="Edmunds Twp"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="5284"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
LOCATION: <input type="text" value="DENNYSVILE-EDMUNDS TL"/>	YEAR BUILT: <input type="text" value="1951"/>	DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRDGNAME: <input type="text" value="STEEL"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="RTE 86 SA 2"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="64"/>	DATE OF INSPECTION: <input type="text" value="9/17/2012"/>
FEATURE UNDER: <input type="text" value="DENNYYS RIVER"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="65"/>
ROAD INV NO: <input type="text" value="000000086X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00086"/>		
ROAD WIDTH: <input type="text" value="22"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Dennysville

CONDITION RATINGS

TOWN1: <input type="text" value="Dennysville"/>	TOWN2: <input type="text" value="Edmunds Twp"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="2881"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="DENNYSVLE-EDMUNDS TL"/>	YEAR BUILT: <input type="text" value="1921"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRDGNAME: <input type="text" value="UPPER"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="Ber Hill Rd"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="105"/>	DATE OF INSPECTION: <input type="text" value="9/17/2012"/>
FEATURE UNDER: <input type="text" value="DENNY'S RIVER"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="76"/>
ROAD INV NO: <input type="text" value="0002904009"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="20"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Edmunds Twp

CONDITION RATINGS

TOWN1: <input type="text" value="Edmunds Twp"/>	TOWN2: <input type="text" value="Dennysville"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="5626"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="IMI SO #86"/>	YEAR BUILT: <input type="text" value="1955"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRDGNAME: DENNYS RIVER	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="#1"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="197"/>	DATE OF INSPECTION: <input type="text" value="9/17/2012"/>
FEATURE UNDER: DENNYS RIVER	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="65.4"/>
ROAD INV NO: <input type="text" value="00000001X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00001"/>		
ROAD WIDTH: <input type="text" value="28"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Edmunds Twp

CONDITION RATINGS

TOWN1: <input type="text" value="Edmunds Twp"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>	
BRIDGE NO.: <input type="text" value="5612"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>	
LOCATION: <input type="text" value="2 MI. S. #86"/>	YEAR BUILT: <input type="text" value="1955"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>	
BRDGNAME: <input type="text" value="NEW HOBART"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>	
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>	
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>	
FEATURE ON: <input type="text" value="US #1"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="167"/>	DATE OF INSPECTION: <input type="text" value="9/17/2012"/>	
FEATURE UNDER: <input type="text" value="NEW HOBART STREAM"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="60.2"/>	
ROAD INV NO: <input type="text" value="00000001X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>		
ROUTE NO: <input type="text" value="00001"/>			
ROAD WIDTH: <input type="text" value="28"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>		
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>			

Structures in the Municipality of Edmunds Twp

CONDITION RATINGS

TOWN1: <input type="text" value="Edmunds Twp"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>	
BRIDGE NO.: <input type="text" value="3171"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>	
LOCATION: <input type="text" value="2 MI. N.E. WHITING"/>	YEAR BUILT: <input type="text" value="1936"/>	DECK CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>	
BRDGNAME: <input type="text" value="TIDE MILL NO. 2"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>	
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="5 Truss"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>	
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>	
FEATURE ON: <input type="text" value="US 1"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="131"/>	DATE OF INSPECTION: <input type="text" value="10/31/2012"/>	
FEATURE UNDER: <input type="text" value="CRANE MILL STREAM"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="23.3"/>	
ROAD INV NO.: <input type="text" value="00000001X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>		
ROUTE NO.: <input type="text" value="00001"/>			
ROAD WIDTH: <input type="text" value="23"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>		
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>			

Structures in the Municipality of Edmunds Twp

CONDITION RATINGS

TOWN1: <input type="text" value="Edmunds Twp"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="2855"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value=".3 MI N/E RTE 1"/>	YEAR BUILT: <input type="text" value="1972"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="TIDE MILL # 1"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="TIDE MILL RD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="57"/>	DATE OF INSPECTION: <input type="text" value="10/5/2012"/>
FEATURE UNDER: <input type="text" value="CRANE MILL BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="85"/>
ROAD INV NO: <input type="text" value="0002900910"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="14"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="LOW USE/REDUNDANT BRIDGE"/>		

Structures in the Municipality of Edmunds Twp

CONDITION RATINGS

TOWN1: <input type="text" value="Edmunds Twp"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRIDGE NO.: <input type="text" value="2374"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
LOCATION: <input type="text" value="2 MI S TOWNLIN"/>	YEAR BUILT: <input type="text" value="1927"/>	DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRDGNAME: HOBART	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="2"/> <input type="text" value="Critical"/>
FEATURE ON: <input type="text" value="HOBARD ROAD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="29"/>	DATE OF INSPECTION: <input type="text" value="12/9/1999"/>
FEATURE UNDER: <input type="text" value="HOBART STREAM"/>	POSTING STATUS: <input type="text" value="2 Closed"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="77.7"/>
ROAD INV NO: <input type="text" value="-1"/>	POSTING TYPE: <input type="text" value="9 Other - lane closure etc."/>	
ROUTE NO: <input type="text" value="0"/>		
ROAD WIDTH: <input type="text" value="21"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="LOW USE/REDUNDANT BRIDGE"/>		