

Structures in the Municipality of Grand Lake Stream Plt

CONDITION RATINGS

TOWN1:	Grand Lake Stream Plt	TOWN2:	No town 2	SUBSTRUCTURE CONDITION	9	Excellent
BRIDGE NO.:	3584	BRIDGE REGION:	Eastern	SUPERSTRUCTURE CONDITION	9	Excellent
LOCATION:	6.8 MI W PASSAMAQUODDY T	YEAR BUILT	2010	DECK CONDITION	9	Excellent
BRDGNAME:	MILFORD STREET	SPAN MATERIAL	7 Precast Concrete	CHANNEL CONDITION:	8	Very Good
OWNER:	1 State DOT	SPAN TYPE:	1 Girder	CULVERT CONDITION:	N	Not Applicable
MAINTAINER	1 State DOT	NUMBER OF MAIN SPANS:	1	APPROACH CONDITION:	4	Poor
FEATURE ON:	MILFORD ST	STRUCTURE LENGTH IN FEET	88	DATE OF INSPECTION:	6/13/2011	
FEATURE UNDER	GRAND LAKE STREAM	POSTING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	77	
ROAD INV NO:	0002900822	POSTING TYPE:	0 None needed			
ROUTE NO:	00000					
ROAD WIDTH	18	FEDERAL BRIDGE INDICATOR:	Y			
CLASS:	BRIDGE ON TOWN WAY OR STATE AID ROAD					

Structures in the Municipality of Grand Lake Stream Plt

CONDITION RATINGS

TOWN1: <input type="text" value="Grand Lake Stream Plt"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRIDGE NO.: <input type="text" value="2596"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
LOCATION: <input type="text" value="0.5 MI E TOWN LINE"/>	YEAR BUILT: <input type="text" value="1997"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="MUSQUASH"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="2"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="GRAND LAKE STREAM"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="131"/>	DATE OF INSPECTION: <input type="text" value="2/6/2013"/>
FEATURE UNDER: <input type="text" value="MUSQUASH STREAM"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="90.6"/>
ROAD INV NO: <input type="text" value="0002900822"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="30"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		