

## Structures in the Municipality of Chester

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Chester"/>	<b>TOWN2:</b> <input type="text" value="Lincoln"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="3790"/>	<b>BRIDGE REGION:</b> <input type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>LOCATION:</b> <input type="text" value="TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1950"/>	<b>DECK CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRDGNAME:</b> <input type="text" value="PENOBSCOT RIVER"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="5 Truss"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="BRIDGE ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="610"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/30/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="PENOBSCOT RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="56.9"/>
<b>ROAD INV NO.:</b> <input type="text" value="0001900965"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO.:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="22"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Lincoln

### CONDITION RATINGS

<b>TOWN1:</b> Lincoln	<b>TOWN2:</b> Mattamiscontis Twp	<b>SUBSTRUCTURE CONDITION:</b> 6 Satisfactory
<b>BRIDGE NO.:</b> 6147	<b>BRIDGE REGION:</b> Eastern	<b>SUPERSTRUCTURE CONDITION:</b> 6 Satisfactory
<b>LOCATION:</b> .8 MI.W. US#2&6	<b>YEAR BUILT:</b> 1971	<b>DECK CONDITION:</b> 5 Fair
<b>BRDGNAME:</b> LEVIN LANCASTER	<b>SPAN MATERIAL:</b> 1 Steel	<b>CHANNEL CONDITION:</b> 6 Satisfactory
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 1 Girder	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 7	<b>APPROACH CONDITION:</b> 7 Good
<b>FEATURE ON:</b> STATE RD	<b>STRUCTURE LENGTH IN FEET:</b> 1122	<b>DATE OF INSPECTION:</b> 11/5/2012
<b>FEATURE UNDER:</b> PENOBSCOT RV	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 86
<b>ROAD INV NO:</b> 000000116X	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00116		
<b>ROAD WIDTH:</b> 32 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> Y	
<b>CLASS:</b> BRIDGE ON STATE HIGHWAY		

## Structures in the Municipality of Lincoln

### CONDITION RATINGS

<b>TOWN1:</b> Lincoln	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> 6 Satisfactory
<b>BRIDGE NO.:</b> 3963	<b>BRIDGE REGION:</b> Eastern	<b>SUPERSTRUCTURE CONDITION:</b> 6 Satisfactory
<b>LOCATION:</b> 200' S OF ROUTE 2&6	<b>YEAR BUILT:</b> 1948	<b>DECK CONDITION:</b> 5 Fair
<b>BRDGNAME:</b> HIGH STREET	<b>SPAN MATERIAL:</b> 1 Steel	<b>CHANNEL CONDITION:</b> 6 Satisfactory
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 1 Girder	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 6 Satisfactory
<b>FEATURE ON:</b> ROUTE 155	<b>STRUCTURE LENGTH IN FEET:</b> 47	<b>DATE OF INSPECTION:</b> 1/9/2013
<b>FEATURE UNDER:</b> MATTANACOOK STREA	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 68.1
<b>ROAD INV NO:</b> 000000155X	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00155		
<b>ROAD WIDTH:</b> 24 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> Y	
<b>CLASS:</b> BRIDGE ON TOWN WAY OR STATE AID ROAD		

## Structures in the Municipality of Lincoln

### CONDITION RATINGS

<b>TOWN1:</b> Lincoln	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> N Not Applicable	
<b>BRIDGE NO.:</b> 2776	<b>BRIDGE REGION:</b> Eastern	<b>SUPERSTRUCTURE CONDITION:</b> N Not Applicable	
<b>LOCATION:</b> .2MI S TOWNLINE	<b>YEAR BUILT:</b> 1924	<b>DECK CONDITION:</b> N Not Applicable	
<b>BRDGNAME:</b> SMITH BROOK	<b>SPAN MATERIAL:</b> 2 Concrete	<b>CHANNEL CONDITION:</b> 5 Fair	
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 4 Culvert	<b>CULVERT CONDITION:</b> 6 Satisfactory	
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 5 Fair	
<b>FEATURE ON:</b> US #2	<b>STRUCTURE LENGTH IN FEET:</b> 12	<b>DATE OF INSPECTION:</b> 11/27/2012	
<b>FEATURE UNDER:</b> SMITH BROOK	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 97.2	
<b>ROAD INV NO:</b> 000000002X	<b>POSTING TYPE:</b> 0 None needed		
<b>ROUTE NO:</b> 00002			
<b>ROAD WIDTH:</b> 0 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N		
<b>CLASS:</b> BRIDGE ON STATE HIGHWAY			

## Structures in the Municipality of Lincoln

### CONDITION RATINGS

<b>TOWN1:</b> Lincoln	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> N Not Applicable
<b>BRIDGE NO.:</b> 2680	<b>BRIDGE REGION:</b> Eastern	<b>SUPERSTRUCTURE CONDITION:</b> N Not Applicable
<b>LOCATION:</b> 1.5 MI NO. TOWNLINE	<b>YEAR BUILT:</b> 2005	<b>DECK CONDITION:</b> N Not Applicable
<b>BRDGNAME:</b> POLLACK BROOK	<b>SPAN MATERIAL:</b> 2 Concrete	<b>CHANNEL CONDITION:</b> 8 Very Good
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 4 Culvert	<b>CULVERT CONDITION:</b> 8 Very Good
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 9 Excellent
<b>FEATURE ON:</b> ROUTE 2	<b>STRUCTURE LENGTH IN FEET:</b> 17	<b>DATE OF INSPECTION:</b> 11/27/2012
<b>FEATURE UNDER:</b> POLLACK BROOK	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 94.2
<b>ROAD INV NO:</b> 000000002X	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00002		
<b>ROAD WIDTH:</b> 0 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON STATE HIGHWAY		

## Structures in the Municipality of Lincoln

### CONDITION RATINGS

<b>TOWN1:</b> Lincoln	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> 7 Good
<b>BRIDGE NO.:</b> 2523	<b>BRIDGE REGION:</b> Eastern	<b>SUPERSTRUCTURE CONDITION:</b> 7 Good
<b>LOCATION:</b> .1 M.L.S.#155	<b>YEAR BUILT:</b> 1989	<b>DECK CONDITION:</b> 7 Good
<b>BRDGNAME:</b> MATTANAWCOOK	<b>SPAN MATERIAL:</b> 7 Precast Concrete	<b>CHANNEL CONDITION:</b> 6 Satisfactory
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 3 Slab	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 8 Very Good
<b>FEATURE ON:</b> RTE.#2-6	<b>STRUCTURE LENGTH IN FEET:</b> 44	<b>DATE OF INSPECTION:</b> 5/9/2011
<b>FEATURE UNDER:</b> MATTANAWCOOK STRE	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 99.6
<b>ROAD INV NO:</b> 000000002X	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00002		
<b>ROAD WIDTH:</b> 44 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> Y	
<b>CLASS:</b> BRIDGE ON STATE HIGHWAY		

## Structures in the Municipality of Lincoln

### CONDITION RATINGS

<b>TOWN1:</b> Lincoln	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> 6 Satisfactory
<b>BRIDGE NO.:</b> 2298	<b>BRIDGE REGION:</b> Eastern	<b>SUPERSTRUCTURE CONDITION:</b> 5 Fair
<b>LOCATION:</b> 1 MI E RTE 2	<b>YEAR BUILT:</b> 1938	<b>DECK CONDITION:</b> 5 Fair
<b>BRDGNAME:</b> FROST STREET	<b>SPAN MATERIAL:</b> 2 Concrete	<b>CHANNEL CONDITION:</b> 6 Satisfactory
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 3 Slab	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 4 Poor
<b>FEATURE ON:</b> FROST STREET	<b>STRUCTURE LENGTH IN FEET:</b> 23	<b>DATE OF INSPECTION:</b> 1/2/2013
<b>FEATURE UNDER:</b> COMBOLASSE STREAM	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 79.4
<b>ROAD INV NO:</b> 0001900845	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00000		
<b>ROAD WIDTH:</b> 26 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> Y	
<b>CLASS:</b> BRIDGE ON TOWN WAY OR STATE AID ROAD		

## Structures in the Municipality of Lincoln

### CONDITION RATINGS

<b>TOWN1:</b> Lincoln	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> 8 Very Good
<b>BRIDGE NO.:</b> 2170	<b>BRIDGE REGION:</b> Eastern	<b>SUPERSTRUCTURE CONDITION:</b> 8 Very Good
<b>LOCATION:</b> 3.2 MI SO TOWNLINE	<b>YEAR BUILT:</b> 2011	<b>DECK CONDITION:</b> 8 Very Good
<b>BRDGNAME:</b> CAMBOLASSE	<b>SPAN MATERIAL:</b> 7 Precast Concrete	<b>CHANNEL CONDITION:</b> 7 Good
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 4 Culvert	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 8 Very Good
<b>FEATURE ON:</b> US #2	<b>STRUCTURE LENGTH IN FEET:</b> 16	<b>DATE OF INSPECTION:</b> 1/23/2012
<b>FEATURE UNDER:</b> CAMBOLASSE STR	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 83.9
<b>ROAD INV NO:</b> 000000002X	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00002		
<b>ROAD WIDTH:</b> 34 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON STATE HIGHWAY		

## Structures in the Municipality of Lincoln

### CONDITION RATINGS

<b>TOWN1:</b> Lincoln	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> 5 Fair
<b>BRIDGE NO.:</b> 2128	<b>BRIDGE REGION:</b> Eastern	<b>SUPERSTRUCTURE CONDITION:</b> 5 Fair
<b>LOCATION:</b> 3 MI SO TOWNLINE	<b>YEAR BUILT:</b> 1915	<b>DECK CONDITION:</b> 5 Fair
<b>BRDGNAME:</b> CARDING MILL	<b>SPAN MATERIAL:</b> 2 Concrete	<b>CHANNEL CONDITION:</b> 7 Good
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 4 Culvert	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 5 Fair
<b>FEATURE ON:</b> US #2	<b>STRUCTURE LENGTH IN FEET:</b> 14	<b>DATE OF INSPECTION:</b> 11/27/2012
<b>FEATURE UNDER:</b> COMBELLASSIE	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 58.3
<b>ROAD INV NO:</b> 000000002X	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00002		
<b>ROAD WIDTH:</b> 38 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON STATE HIGHWAY		

## Structures in the Municipality of Lincoln

### CONDITION RATINGS

<b>TOWN1:</b> Lincoln	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> N Not Applicable
<b>BRIDGE NO.:</b> 0892	<b>BRIDGE REGION:</b> Eastern	<b>SUPERSTRUCTURE CONDITION:</b> N Not Applicable
<b>LOCATION:</b> .4MI E RTE 2	<b>YEAR BUILT:</b> 1984	<b>DECK CONDITION:</b> N Not Applicable
<b>BRDGNAME:</b> SOUTH LINCOLN	<b>SPAN MATERIAL:</b> 1 Steel	<b>CHANNEL CONDITION:</b> 5 Fair
<b>OWNER:</b> 4 Municipal	<b>SPAN TYPE:</b> 4 Culvert	<b>CULVERT CONDITION:</b> 6 Satisfactory
<b>MAINTAINER:</b> 4 Municipal	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 8 Very Good
<b>FEATURE ON:</b> STATION RD	<b>STRUCTURE LENGTH IN FEET:</b> 12	<b>DATE OF INSPECTION:</b> 2/12/2013
<b>FEATURE UNDER:</b> POLLACK BROOK	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 94
<b>ROAD INV NO:</b> 0001900727	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00000		
<b>ROAD WIDTH:</b> 0 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON TOWN WAY		

## Structures in the Municipality of Lincoln

### CONDITION RATINGS

<b>TOWN1:</b> Lincoln	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> N Not Applicable
<b>BRIDGE NO.:</b> 0876	<b>BRIDGE REGION:</b> Eastern	<b>SUPERSTRUCTURE CONDITION:</b> N Not Applicable
<b>LOCATION:</b> 1.1 MI E RT 2	<b>YEAR BUILT:</b> 1985	<b>DECK CONDITION:</b> N Not Applicable
<b>BRDGNAME:</b> CAMBOLASSE	<b>SPAN MATERIAL:</b> 1 Steel	<b>CHANNEL CONDITION:</b> 6 Satisfactory
<b>OWNER:</b> 4 Municipal	<b>SPAN TYPE:</b> 4 Culvert	<b>CULVERT CONDITION:</b> 6 Satisfactory
<b>MAINTAINER:</b> 4 Municipal	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 6 Satisfactory
<b>FEATURE ON:</b> TOWN FARM RD	<b>STRUCTURE LENGTH IN FEET:</b> 12	<b>DATE OF INSPECTION:</b> 11/27/2012
<b>FEATURE UNDER:</b> CAMBOLASSE STREAM	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 83.2
<b>ROAD INV NO:</b> 0001901617	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00000		
<b>ROAD WIDTH:</b> 0 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON TOWN WAY		