

Structures in the Municipality of Littleton

CONDITION RATINGS

TOWN1: <input type="text" value="Littleton"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRIDGE NO.: <input type="text" value="6204"/>	BRIDGE REGION: <input type="text" value="Northern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="0.2 MI NORTH OF TOWN LINE"/>	YEAR BUILT: <input type="text" value="1992"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="MCIVER"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="3 Slab"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="BACK RIDGE ROAD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="44"/>	DATE OF INSPECTION: <input type="text" value="10/10/2012"/>
FEATURE UNDER: <input type="text" value="B STREAM"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="86"/>
ROAD INV NO: <input type="text" value="0000301315"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="26"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Littleton

CONDITION RATINGS

TOWN1: <input type="text" value="Littleton"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="5771"/>	BRIDGE REGION: <input type="text" value="Northern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="1.2 MI N OF JCT SHAW RD"/>	YEAR BUILT: <input type="text" value="1989"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="FRAMINGHAM ROAD"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="2"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="FRAMINGHAM ROAD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="22"/>	DATE OF INSPECTION: <input type="text" value="10/10/2012"/>
FEATURE UNDER: <input type="text" value="MCGARY BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="100"/>
ROAD INV NO: <input type="text" value="0000301327"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Littleton

CONDITION RATINGS

TOWN1: Littleton	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 5273	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: .4 MI W JCT US 1	YEAR BUILT: 1949	DECK CONDITION: N Not Applicable
BRDGNAME: WILEY ROAD	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 7 Good
OWNER: 4 Municipal	SPAN TYPE: 6 Arch	CULVERT CONDITION: 6 Satisfactory
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: WILEY RD	STRUCTURE LENGTH IN FEET: 16	DATE OF INSPECTION: 8/8/2012
FEATURE UNDER: BIG BROOK	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 92.7
ROAD INV NO: 0000301362	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: N	
CLASS: MINOR SPAN ON TOWN WAY		

Structures in the Municipality of Littleton

CONDITION RATINGS

TOWN1: <input type="text" value="Littleton"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="5044"/>	BRIDGE REGION: <input type="text" value="Northern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="1.2 MI E JCT US 1"/>	YEAR BUILT: <input type="text" value="1948"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="JARVIS"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="2"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="CARSON RD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="18"/>	DATE OF INSPECTION: <input type="text" value="8/8/2012"/>
FEATURE UNDER: <input type="text" value="BIG BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="65.7"/>
ROAD INV NO: <input type="text" value="0000301364"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

Structures in the Municipality of Littleton

CONDITION RATINGS

TOWN1: <input type="text" value="Littleton"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="1110"/>	BRIDGE REGION: <input type="text" value="Northern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
LOCATION: <input type="text" value="2.7 MI. E. RT. 1"/>	YEAR BUILT: <input type="text" value="1985"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="WATSON"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="SA9 (CARSON RD.)"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="137"/>	DATE OF INSPECTION: <input type="text" value="10/10/2012"/>
FEATURE UNDER: <input type="text" value="MEDUXNEKEAG RIVER"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="95.9"/>
ROAD INV NO: <input type="text" value="0000301364"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="25"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Littleton

CONDITION RATINGS

TOWN1: <input type="text" value="Littleton"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="1006"/>	BRIDGE REGION: <input type="text" value="Northern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
LOCATION: <input type="text" value=".1 west of foxcroft road"/>	YEAR BUILT: <input type="text" value="1911"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="WATSON COVERED"/>	SPAN MATERIAL: <input type="text" value="3 Wood"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="5 Truss"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="2"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON: <input type="text" value="Carson Road"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="169"/>	DATE OF INSPECTION: <input type="text" value="9/27/2012"/>
FEATURE UNDER: <input type="text" value="Meduxnekeag River"/>	POSTING STATUS: <input type="text" value="2 Closed"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="-2"/>
ROAD INV NO: <input type="text" value="-1"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="-"/>		
ROAD WIDTH: <input type="text" value="-3"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		