

Structures in the Municipality of Rangeley Plt

CONDITION RATINGS

TOWN1: Rangeley Plt	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 5772	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 2.2 MI E OF JCT RTE 17	YEAR BUILT: 1960	DECK CONDITION: 6 Satisfactory
BRDGNAME: SOUTH BOG	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 5 Fair
OWNER: 1 State DOT	SPAN TYPE: 3 Slab	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 2	APPROACH CONDITION: 4 Poor
FEATURE ON: SOUTH SHORE ROAD	STRUCTURE LENGTH IN FEET: 56	DATE OF INSPECTION: 11/13/2012
FEATURE UNDER: SOUTH BOG STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 84.1
ROAD INV NO: 0000701300	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 26 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Rangeley Plt

CONDITION RATINGS

TOWN1: Rangeley Plt	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 4 Poor
BRIDGE NO.: 1815	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 8.2 MI NORTH RTE 17	YEAR BUILT: 1920	DECK CONDITION: 5 Fair
BRDGNAME: BEMIS STREAM	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 5 Fair
OWNER: 7 Private	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 7 Private	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 3 Serious
FEATURE ON: TOWN WAY	STRUCTURE LENGTH IN FEET: 32	DATE OF INSPECTION: 9/10/2001
FEATURE UNDER: BEMIS STREAM	POSTING STATUS: 7 Other - Lane Closur	FEDERAL SUFFICIENCY RATING: 50
ROAD INV NO: 0000700859	POSTING TYPE: 4 Speed limit for weight purposes (no weight restriction)	
ROUTE NO: 00000	FEDERAL BRIDGE INDICATOR: Y	
ROAD WIDTH: 9 FEET		
CLASS: LOW USE/REDUNDANT BRIDGE		