

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="2819"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="2.3 MI EAST 150"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1955"/>	<b>DECK CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="SUCY"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input style="width: 20px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
<b>MAINTAINER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="US #2"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="21"/>	<b>DATE OF INSPECTION:</b> <input style="width: 60px;" type="text" value="12/6/2011"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="STONY BROOK"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="78.5"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000002X"/>	<b>POSTING TYPE:</b> <input style="width: 100px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 50px;" type="text" value="00002"/>		
<b>ROAD WIDTH:</b> <input style="width: 40px;" type="text" value="0"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="N"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="1082"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value=".2 MI S RT 201"/>	<b>YEAR BUILT:</b> <input type="text" value="1990"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="LAMBERT"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="6 Arch"/>	<b>CULVERT CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="LAMBERT ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="12"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/10/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="LAMBERT BRK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="94.5"/>
<b>ROAD INV NO:</b> <input type="text" value="0002500397"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="1084"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="1 MI N RT 150"/>	<b>YEAR BUILT:</b> <input type="text" value="1978"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="COLD BROOK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="6 Arch"/>	<b>CULVERT CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>FEATURE ON:</b> <input type="text" value="STEWART HILL RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="22"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="7/17/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="COLD BK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="65.6"/>
<b>ROAD INV NO:</b> <input type="text" value="0002520145"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="LOW USE/REDUNDANT BRIDGE"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input style="width: 60px;" type="text" value="1090"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input style="width: 140px;" type="text" value="0.5 MI N ROUTE 201"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1995"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <b>HATHAWAY STREET</b>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="8"/> <input style="width: 100px;" type="text" value="Very Good"/>
<b>OWNER:</b> <input style="width: 90px;" type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 50px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>FEATURE ON:</b> <input style="width: 110px;" type="text" value="HATHAWAY STREET"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 50px;" type="text" value="16"/>	<b>DATE OF INSPECTION:</b> <input style="width: 100px;" type="text" value="11/9/2011"/>
<b>FEATURE UNDER:</b> <input style="width: 110px;" type="text" value="CURRIER BK"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="100"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="0002520046"/>	<b>POSTING TYPE:</b> <input style="width: 90px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input style="width: 60px;" type="text" value="0"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="N"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>BRIDGE NO.:</b> <input type="text" value="1091"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>LOCATION:</b> <input type="text" value=".1 MI NE JCT 2,201"/>	<b>YEAR BUILT:</b> <input type="text" value="1935"/>	<b>DECK CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>BRDGNAME:</b> <input type="text" value="MILL STREET"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="1"/> <input type="text" value="Imminent Failure"/>
<b>FEATURE ON:</b> <input type="text" value="MILL ST"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="27"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/9/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="CURRIER BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="2 Closed"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="47"/>
<b>ROAD INV NO:</b> <input type="text" value="0002520068"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="27"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRIDGE NO.:</b> <input type="text" value="2444"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>LOCATION:</b> <input type="text" value="2.0*MI*W*TOWNLIN"/>	<b>YEAR BUILT:</b> <input type="text" value="1939"/>	<b>DECK CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRDGNAME:</b> <input type="text" value="LAMBERT BROOK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="RTE 2"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="15"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/13/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="LAMBERT BK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="42.4"/>
<b>ROAD INV NO:</b> <input type="text" value="000000002X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00002"/>		
<b>ROAD WIDTH:</b> <input type="text" value="30"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>	
<b>BRIDGE NO.:</b> <input type="text" value="2617"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>	
<b>LOCATION:</b> <input type="text" value="JCT 2&amp;201"/>	<b>YEAR BUILT:</b> <input type="text" value="1976"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>	
<b>BRDGNAME:</b> <input type="text" value="MARGARET CHASE SMITH N"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>	
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>	
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>	
<b>FEATURE ON:</b> <input type="text" value="US2 &amp; US201"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="132"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/22/2012"/>	
<b>FEATURE UNDER:</b> <input type="text" value="KENNEBEC RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="64.1"/>	
<b>ROAD INV NO:</b> <input type="text" value="000000002X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>		
<b>ROUTE NO:</b> <input type="text" value="00002"/>			
<b>ROAD WIDTH:</b> <input type="text" value="40"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>		
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>			

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="3"/> <input style="width: 80px;" type="text" value="Serious"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="1074"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="3"/> <input style="width: 80px;" type="text" value="Serious"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="2005"/>	<b>DECK CONDITION:</b> <input style="width: 20px;" type="text" value="2"/> <input style="width: 80px;" type="text" value="Critical"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="OLD WESSERUNSET"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="6 Arch"/>	<b>CULVERT CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 20px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="107"/>	<b>DATE OF INSPECTION:</b> <input style="width: 60px;" type="text" value="5/24/1996"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="2 Closed"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 40px;" type="text" value="-2"/>
<b>ROAD INV NO:</b> <input style="width: 50px;" type="text" value="-1"/>	<b>POSTING TYPE:</b> <input style="width: 90px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 50px;" type="text" value="-"/>		
<b>ROAD WIDTH:</b> <input style="width: 50px;" type="text" value="-3"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px; height: 40px;" type="text"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="2785"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="JCT 2&amp;201"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1976"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input style="width: 130px;" type="text" value="MARGARET CHASE SMITH S"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="US2 &amp; US201"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 50px;" type="text" value="182"/>	<b>DATE OF INSPECTION:</b> <input style="width: 100px;" type="text" value="9/25/2012"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="KENNEBEC RIVER"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="64.3"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000002X"/>	<b>POSTING TYPE:</b> <input style="width: 100px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00002"/>		
<b>ROAD WIDTH:</b> <input style="width: 50px;" type="text" value="37"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="6215"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>LOCATION:</b> <input style="width: 120px;" type="text" value=".1 MI E MALBONS MILL RD"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1972"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="5"/> <input style="width: 100px;" type="text" value="Fair"/>
<b>BRDGNAME:</b> MALBONS MILLS	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="NOTCH RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 50px;" type="text" value="81"/>	<b>DATE OF INSPECTION:</b> <input style="width: 60px;" type="text" value="6/1/2011"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="WESSERUNSETT STREA"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="97.7"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="0002500410"/>	<b>POSTING TYPE:</b> <input style="width: 100px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input style="width: 40px;" type="text" value="28"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="LOW USE/REDUNDANT BRIDGE"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="2924"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="2.4 MI E JCT RTE 150"/>	<b>YEAR BUILT:</b> <input type="text" value="1942"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="WESSERUNSETT"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 2"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="234"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="7/18/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="WESSERUNSETT STREA"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="75.9"/>
<b>ROAD INV NO:</b> <input type="text" value="000000002X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00002"/>		
<b>ROAD WIDTH:</b> <input type="text" value="29"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="2965"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="5"/> <input style="width: 100px;" type="text" value="Fair"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value=".1 MI E US 2"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1953"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="5"/> <input style="width: 100px;" type="text" value="Fair"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="WOOLEN MILL"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="8"/> <input style="width: 100px;" type="text" value="Very Good"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="5"/> <input style="width: 100px;" type="text" value="Fair"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="201"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="22"/>	<b>DATE OF INSPECTION:</b> <input style="width: 100px;" type="text" value="12/8/2011"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="CURRIER BROOK"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="69.4"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000201X"/>	<b>POSTING TYPE:</b> <input style="width: 100px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00201"/>		
<b>ROAD WIDTH:</b> <input style="width: 50px;" type="text" value="40"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="N"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="3302"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value=".5 MI S TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1958"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="COLD BROOK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>FEATURE ON:</b> <input type="text" value="201"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="21"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/3/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="COLD BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="85.8"/>
<b>ROAD INV NO:</b> <input type="text" value="000000201X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00201"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="3773"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.1 Mi N OFJCT NOTCH RD"/>	<b>YEAR BUILT:</b> <input type="text" value="1969"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> WEST RIDGE	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="MALBONS MILLS ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="85"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/23/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="W BR WESSERUNSETT S"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="84.4"/>
<b>ROAD INV NO:</b> <input type="text" value="0002520058"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="28"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="6106"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value=".3 MI S JCT #201"/>	<b>YEAR BUILT:</b> <input type="text" value="1966"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="CURRIER BROOK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="RTE 104"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="10"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="12/6/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="CURRIER BRK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="98.2"/>
<b>ROAD INV NO:</b> <input type="text" value="000000104X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00104"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input type="text" value="Canaan"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRIDGE NO.:</b> <input type="text" value="6138"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>LOCATION:</b> <input type="text" value=".2 MI W RTE #23"/>	<b>YEAR BUILT:</b> <input type="text" value="1936"/>	<b>DECK CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRDGNAME:</b> <input type="text" value="HILTON BRIDGE"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="5 Truss"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>FEATURE ON:</b> <input type="text" value="RED BRIDGE RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="65"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="1/9/2013"/>
<b>FEATURE UNDER:</b> <input type="text" value="CARRABASSET STR"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="58.3"/>
<b>ROAD INV NO:</b> <input type="text" value="0002500402"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="18"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="LOW USE/REDUNDANT BRIDGE"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="6152"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value=".3 MI S TOWNLINE"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1966"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="5"/> <input style="width: 100px;" type="text" value="Fair"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="SMITH POND"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="4"/> <input style="width: 100px;" type="text" value="Poor"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="ROUTE 150"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 50px;" type="text" value="116"/>	<b>DATE OF INSPECTION:</b> <input style="width: 100px;" type="text" value="5/23/2012"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="W BR WESSERUNSETT S"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="83.1"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000150X"/>	<b>POSTING TYPE:</b> <input style="width: 100px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00150"/>		
<b>ROAD WIDTH:</b> <input style="width: 50px;" type="text" value="28"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Skowhegan

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Skowhegan"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="2661"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="1 MI SO TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1955"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> PERKINS	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="#150"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="14"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/7/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="COLD BRK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="99.5"/>
<b>ROAD INV NO:</b> <input type="text" value="000000150X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00150"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		