

Structures in the Municipality of Twp 02 R 08 Nwp

CONDITION RATINGS

TOWN1: <input type="text" value="Twp 02 R 08 Nwp"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="6075"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
LOCATION: <input type="text" value="2.6 MI N OF TL"/>	YEAR BUILT: <input type="text" value="1966"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRDGNAME: <input type="text" value="I95 SB / CPRR"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="I-95 SOUTHBOUND"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="182"/>	DATE OF INSPECTION: <input type="text" value="7/10/2012"/>
FEATURE UNDER: <input type="text" value="C.P. RAILROAD"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="94"/>
ROAD INV NO: <input type="text" value="000000095S"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00095"/>		
ROAD WIDTH: <input type="text" value="43"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Twp 02 R 08 Nwp

CONDITION RATINGS

TOWN1: <input type="text" value="Twp 02 R 08 Nwp"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="6074"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="INTERCHANGE 227"/>	YEAR BUILT: <input type="text" value="1966"/>	DECK CONDITION: <input type="text" value="9"/> <input type="text" value="Excellent"/>
BRDGNAME: <input type="text" value="LINCOLN SPUR / I 95"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="6"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="FAP 49"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="458"/>	DATE OF INSPECTION: <input type="text" value="6/23/2011"/>
FEATURE UNDER: <input type="text" value="I-95 (NB & SB)"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="83"/>
ROAD INV NO: <input type="text" value="0001901887"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="28"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Twp 02 R 08 Nwp

CONDITION RATINGS

TOWN1: <input type="text" value="Twp 02 R 08 Nwp"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>	
BRIDGE NO.: <input type="text" value="6073"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>	
LOCATION: <input type="text" value=".3 ML.N. TOWNLINE"/>	YEAR BUILT: <input type="text" value="1966"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>	
BRDGNAME: <input type="text" value="I95 SB / MATTAMISCONTIS"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>	
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>	
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>	
FEATURE ON: <input type="text" value="I-95 SOUTHBOUND"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="123"/>	DATE OF INSPECTION: <input type="text" value="1/23/2013"/>	
FEATURE UNDER: <input type="text" value="MATTAMISCONTIS STRE"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="97.7"/>	
ROAD INV NO: <input type="text" value="000000095S"/>	POSTING TYPE: <input type="text" value="0 None needed"/>		
ROUTE NO: <input type="text" value="00095"/>			
ROAD WIDTH: <input type="text" value="43"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>		
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>			

Structures in the Municipality of Twp 02 R 08 Nwp

CONDITION RATINGS

TOWN1: <input type="text" value="Twp 02 R 08 Nwp"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>	
BRIDGE NO.: <input type="text" value="1415"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>	
LOCATION: <input type="text" value=".3 MI NO TOWNLINE"/>	YEAR BUILT: <input type="text" value="1975"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>	
BRDGNAME: <input type="text" value="I95 NB / MATTAMISCONTIS ST"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>	
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>	
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>	
FEATURE ON: <input type="text" value="I-95 NORTHBOUND"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="90"/>	DATE OF INSPECTION: <input type="text" value="4/30/2012"/>	
FEATURE UNDER: <input type="text" value="MATTAMISCONTIS STRE"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="96.5"/>	
ROAD INV NO: <input type="text" value="000000095X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>		
ROUTE NO: <input type="text" value="00095"/>			
ROAD WIDTH: <input type="text" value="41"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>		
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>			

Structures in the Municipality of Twp 02 R 08 Nwp

CONDITION RATINGS

TOWN1: <input type="text" value="Twp 02 R 08 Nwp"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>	
BRIDGE NO.: <input type="text" value="1414"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>	
LOCATION: <input type="text" value="2.6 MI N OF TOWN LINE"/>	YEAR BUILT: <input type="text" value="1975"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>	
BRDGNAME: <input type="text" value="I 95 NB / C P RR"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>	
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>	
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>	
FEATURE ON: <input type="text" value="I-95 NORTHBOUND"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="174"/>	DATE OF INSPECTION: <input type="text" value="7/10/2012"/>	
FEATURE UNDER: <input type="text" value="C. P. RAILROAD"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="94.8"/>	
ROAD INV NO: <input type="text" value="000000095X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>		
ROUTE NO: <input type="text" value="00095"/>			
ROAD WIDTH: <input type="text" value="41"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>		
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>			